

BRANTLY SERVICE BULLETIN INDEX

PAGE 1 OF 1
27 February, 2007

<u>SB. NO.</u>	<u>SERIALS</u>	<u>TITLE</u>	<u>COMPLIANCE</u>	<u>REMARKS</u>
1	001 thru 031	Tail Rotor Guard & Skid Assembly Replacement		
2	001 thru 031	Tail Rotor Drive Modification		
3A	All B-2 Models	Tail Rotor Drive Inspection		
4	001 thru 043	Elimination of Fretting Corrosion & Improvement of Tail Rotor Drive Fatigue Strength	N/L/T 25 Hr. Inspection	Refer to SK#6
5	001 thru 044	Tailcone Reinforcement	N/L/T 25 Hr. Inspection	Refer to SK#9
6	001 thru 060	Main Rotor Drive Bolts & Centrifugal Clutch Inspection & Modification	N/L/T 50 Flight Hrs.	Refer to SK#10
7	001 thru 056	Modification of Landing Gear	N/L/T 31-March-61	Refer to SK#12
8	001 thru 063	Fuel Line Inspection	Immediately	
9	See Bulletin	Main Transmission Forward Mount Rework	N/L/T 25 Flight Hrs.	
10	See Bulletin	Modification of Tail Rotor Guard	N/L/T 25 Hr. Inspection	
11	See Bulletin	Rod End Bearing Replacement	ASAP	
12	001 thru 094	Elimination of Carburetor Manifold From Oil System	ASAP	Refer to SK#17
13	001 thru 103	Seat Safety Bracket	N/L/T 25 Flight Hrs.	Refer to SK#19
14	001 thru 102	Transmission Mount Modification	N/L/T 25 Flight Hrs.	Refer to SK#20
15	001 thru 111	Increased Tail Rotor Control	N/L/T 10 Flight Hrs.	
16	See Bulletin	Fuel Pump Conversion	N/L/T 25 Flight Hrs.	Refer to SK#27
17	001 thru 193	Oil Pressure Gauge Line Fitting Chafing Against Engine Mount Structure	N/L/T 25 Hr. Inspection	Refer to SK#36
18	See Bulletin	Conversion of Lear Fuel Pumps	N/L/T 25 Flight Hrs.	Refer to SK#35
19	See Bulletin	Replacement of Rudder Control Post Upper Attach Bracket	N/L/T 25 Hr. Inspection	
20	001 thru 453	Tail Rotor Blade Inspection	N/L/T 25 Flight Hrs.	
21	001 thru 306	Replacement of Main Transmission Upper Mast Bearing	N/L/T 100 Hr. Inspection	
B2B-68-1	All B2, B2A, B2B	Tail Rotor Spar Inspection	Immediately	
B2B-68-2A	All Models	Inspection & Corrosion Proofing of the Tail Rotor Drive Shaft	N/L/T 10 Flight Hrs.	
B2B-68-3	All B2, B2A, B2B	Inspection of Stabilizer Attachment Bolts	N/L/T 100 Hr. Inspection	
BV-96-01	All B2, B2A, B2B Up to S/N 2022	Seat Belt Contacting Fuel Return Line	N/L/T 25 Flight Hrs.	
101	See Bulletin	Glare from Landing Lights	Owner's Discretion	
102	All Models	Chaffing on Battery Cables	Owner's Discretion	
105A	See Bulletin	Tail Drive System Inspection	N/L/T 10 Flight Hrs.	
106	See Bulletin	Intermediate Tail Rotor Drive	N/L/T 10 Flight Hrs.	
110	See Bulletin	Tail Rotor Hub	N/L/T 10 Flight Hrs.	