

SERVICE BULLETIN No: 102
REVISION: 21 Nov. 2002
SUBJECT: Chaffing on battery cables.
MODELS AFFECTED: All B-2 series helicopters.
TIME OF COMPLIANCE: Owner's Discretion.
FAA APPROVAL: This service bulletin is FAA approved.

Purpose: The purpose of this service bulletin is to prevent chaffing on the battery cables.

Inspection: Check for chaffing on both cables coming out of the battery box. If chaffing is found then apply the corrective action described below.

Corrective action: Replace the affected cable and add a clamp to prevent the chaffing from reoccurring.

If you have any questions about servicing your Brantly helicopter, please don't hesitate to contact our service department.

Service Department, service@brantly.com
Brantly International Inc.
12399 Airport Drive, Vernon, TX, 76384, USA
Tel. (940) 552-5451, Fax. (940) 552-2703,