

SERVICE BULLETIN No: 110
REVISION: ~
SUBJECT: Tail Rotor Hub
MODELS AFFECTED: See below.
TIME OF COMPLIANCE: See below.
FAA APPROVAL: FAA Approved 2/21/07

(Prepared 08 Nov 2006)

Introduction

Some tail rotor hubs p/n 2951 have a defect and must be replaced. Brantly International will supply a new replacement part to each customer upon return of the original. See the details and contact information below.

Applicability

Applies to models B-2, B-2A, or B-2B that have a p/n 2951 tail rotor hub installed with the following serial numbers: BI018, BI019, BI020, BI021, BI022, BI023, BI024, BI025, BI026, BI027, and BI028.

NOTE	The serial number is located on the hub near the center. It may be viewed without disassembling.
-------------	--------------------------------------------------------------------------------------------------

Compliance

Within the next 10 hours time in service after the effective date of this service bulletin, remove the tail rotor hub (with the serial numbers mentioned above) from the helicopter per the Brantly maintenance instructions and replace it with a new part. See the contact information for obtaining the new part.

Contact

Purchasing Department (purchasing@brantly.com)
Brantly International Inc.
12399 Airport Dr.
Vernon, TX 76384
Phn. (940) 552-5451